

Yealink USB Connect Release Notes of Version **32**

Table of Contents

Yea	link USB Connect Release Notes of Version 32	1	
Yea	link USB Connect Release Notes of Version 32 0.32.85.0	2	
1.	Introduction	2	
2.	Feature List	2	
3.	Optimization	2	
4.	Bug Fixes	2	
Yea	Yealink USB Connect Release Notes of Version 32 0.32.80.03		
1.	Introduction	3	
2.	Feature List	3	
3.	Optimization	3	
4.	Bug Fixes	3	
Yea	Yealink USB Connect Release Notes of Version 32 0.32.69.04		
1.	Introduction	4	
2.	Feature List	4	
3.	Optimization	5	
4.	Bug Fixes	5	
Yea	Yealink USB Connect Release Notes of Version 0.3.36.0 for MAC6		
1.	Introduction	6	
2.	Feature List	6	
3.	Optimization	6	
4.	Bug Fixes	6	
Yea	link USB Connect Release Notes of Version 0.3.36.0 for Windows & 0.3.13.0 fo	r	
MA	C	7	
1.	Introduction	7	
2.	Feature List	7	
3.	Optimization	7	
4.	Bug Fixes	7	
Yea	link USB Connect Release Notes of Version 30 0.3.16.0	8	
1.	Introduction	8	
2.	Feature List	8	
3.	Optimization	8	
4.	Bug Fixes	8	
5.	Features Descriptions	9	



Yealink USB Connect Release Notes of Version 32 0.32.85.0

1. Introduction

Firmware Version:

Yealink USB Connect: 0.32.85.0 for Windows

Yealink USB Connect: 0.32.85.0 for MAC (macOS running on Intel chip, not Apple M1 chip)

- Applicable Models: CP900, CP700, UH36, BT50, UVC30, UH33 E2, UVC40, UH34, UVC20, WH62, WH63, WH66, WH67, MP50
- Release Date: May 10th, 2021.

2. Feature List

None

3. Optimization

None

4. Bug Fixes

 Fixed an issue that Yealink USB Connect could not recognize Bria Enterprise, Bria 5, and Bria softphones. You can choose Yealink headset/speakerphone as Bria's audio device and perform call control.



Yealink USB Connect Release Notes of Version 32 0.32.80.0

1. Introduction

Firmware Version:

Yealink USB Connect: 0.32.80.0 for Windows

Yealink USB Connect: 0.32.80.0 for MAC (macOS running on Intel chip, not Apple M1 chip)

- Applicable Models: CP900, CP700, UH36, BT50, UVC30, UH33 E2, UVC40, UH34, UVC20, WH62, WH63, WH66, WH67, MP50
- Release Date: Mar 3th, 2021.

2. Feature List

- 1. Added support for the new hardware version UVC40.
- 2. Supported WH6X DECT wireless headsets of the V20 version. For example, the Mute reminder configuration value has been modified according to the silence detection.

3. Optimization

1. Optimized the upgrade rules for CP700 and CP900 devices.

4. Bug Fixes

- 1. Fixed an issue that YMCS may fail to export the software log.
- 2. Fixed an issue that the prompt of the pop-up box is incorrect when exporting the log.
- 3. Fixed an issue that as the conflict between Yealink USB Connect and Yealink UME, the image configuration parameters are incorrect on the UVC series devices.



Yealink USB Connect Release Notes of Version 32 0.32.69.0

1. Introduction

Firmware Version:

Yealink USB Connect: 0.32.69.0 for Windows

Yealink USB Connect: 0.32.69.0 for MAC

Applicable Models: CP900, CP700, UH36, BT50, UVC30, UH33 E2, UVC40

Release Date: Dec 27th, 2020.

2. Feature List

- 1. Supported new device models, including UH33 E2, UVC40.
- 2. Supported changing the field of view for UVC30, the adjustable angles are: 70°, 90°, and 120°.
- Supported synchronizing the time on USB device (should support this feature) with the time on PC every 1 minute.
- 4. Provided API for integrating with the third-party softphone (Counterpath_Bria, Broadsoft UC One, Avaya).
- 5. Supported the feature when there are multiple softphones on PC, you can set the softphone to be woken up by the headset first.
- 6. Supported the local ringtone feature for YHC20 (UH36).
- 7. Added "About" button, including Check for updates and Feedback.
- 8. Added a pop-up window when closing the software during firmware upgrade.
- 9. Supported uploading a screenshot in *.jpeg or *.jpe format when giving feedback.
- 10. Added the "Update more devices" button on the update device page when connecting multiple devices of the same model.
- 11. Supported automatic updates and prompts for the enhanced versions of security and stability.



12. Supported restrictions on downgrading UVC30/UVC40, and prohibit users from downgrading some models to an older version.

3. Optimization

- 1. Optimized the UI interface:
- a) Replaced the original client logo on the "Update device" page with the corresponding device picture.
 - b) The translations of the audio collection button are optimized to **Start** and **Stop**.
- c) Added **Device Settings** module, which only appears for devices that support this configuration.
- 2. Improved the detection speed when multiple devices of the same model are connected.
- 3. Optimized the experience and stability for upgrading devices.

4. Bug Fixes

- Fixed an issue that when USB device connects to software, the device type reported to YMCS/YDMP will be incorrect.
- 2. Fixed an issue that the device may crash in some scenarios.



Yealink USB Connect Release Notes of Version

0.3.36.0 for MAC

1. Introduction

Firmware Version:

Yealink USB Connect: 0.3.36.0 for MAC

- Applicable Models: CP900, CP700, UH36, BT50, YHC20
- Release Date: June 8th, 2020.

2. Feature List

1. Support BT50 firmware upgrade.

After the upgrade, BT50 cannot be downgraded to an earlier firmware version.

3. Optimization

None

4. Bug Fixes

None



Yealink USB Connect Release Notes of Version

0.3.36.0 for Windows & 0.3.13.0 for MAC

1. Introduction

Firmware Version:

Yealink USB Connect: 0.3.36.0 for Windows

Yealink USB Connect: 0.3.13.0 for MAC

Applicable Models: CP900, CP700, UH36, BT50, YHC20

Release Date: April 19th, 2020.

2. Feature List

1. Support five languages, (Chinese/English/Deutsch/French/Japanese).

User now could configure the software close button "X" as completely exit or run in the background.

User now have the ability to drag and drop firmware to the device CARDS and go into the upgrade prompt box.

4. New Application for MAC system.

3. Optimization

- 1. System protection optimization: battery power below 10% is not allowed to upgrade.
- Display optimization: when multi-device connected, the software UI will directly show the card interface.

4. Bug Fixes

 Fixed an issue that when DFU and HID protocol device connect to software, the UI will crash sometime.



Yealink USB Connect Release Notes of Version 30 0.3.16.0

1. Introduction

Firmware Version:

Yealink USB Connect: 0.3.16.0

Applicable Models: CP900, CP700, UH36, BT50, YHC20

• Release Date: Mar 19th, 2020.

2. Feature List

- 1. Device information.
- 2. Device upgrade.
- 3. Device diagnose.
- 4. Device recover.
- 5. Device feedback.
- 6. Pair management. (New)
- 7. Upgrade BT50 via DFU or HID. (New)
- 8. Pair CP900/CP700 with BT50 via Bluetooth. (New)
- 9. Support new headset model UH36 (YHC20). (New)

3. Optimization

 Improved the security, that convert protocol-related dll into static library links, and pack the logical dll and exe.

4. Bug Fixes

 Fixed an issue that the device may crash after selecting the BIN file in the upgrade interface, the client prompts the firmware do not match, and returns to the idle, the USB



device will not upgrade.

5. Features Descriptions

1. Device information.

Description: After connecting Yealink USB devices to your computer with Yealink USB Connect installed, you can view the device information on the USB device manager client.


- The available information includes:
- Device model
- Firmware version
- SN
- Paired status
- Bluetooth switch (New)
- Enable built-in ringtone (New)

2. Pair management. (New)

Description: If you insert Yealink USB Dongle BT50 to your PC, you can find **Pair Management** function from the navigation bar on the left side of the page. With this function, you can easily pair BT50 with Yealink CP devices.

(1) Search for device

When CP900/CP700 is connected to the PC via USB or is in the Bluetooth pairing mode, click **Refresh** on the **Pair Management** page to search for the devices that can be currently paired with.



(2) Device pairing & connection



When there is a device that can be paired with, click **Start Pairing** to pair and connect the device.