

Yealink VC210 Teams Collaboration Bar Release Notes of Version 15

Table of Contents

Yealink VC210 Teams Collaboration Bar Release Notes of Version 15	1
Yealink VC210 Teams Collaboration Bar Release Notes of Version 118.15.0.23	2
1. Introduction.....	2
2. Feature List.....	2
3. Optimization	2
4. Bug Fixes.....	2
Yealink VC210 Teams Collaboration Bar Release Notes of Version 118.15.0.20	3
1. Introduction.....	3
2. Feature List.....	3
3. Optimization	3
4. Bug Fixes.....	3
5. Features Descriptions.....	3

Yealink VC210 Teams Collaboration Bar Release Notes of Version 118.15.0.23

1. Introduction

- Firmware Version: 118.15.0.23
- Teams Version: 1449/1.0.94.2020040901
- Partner APP Version: 1.15.0.20040919
- Applicable Models: VC210
- CP900 Firmware: 100.420.0.15
- Release Date: June 3rd, 2020.

2. Feature List

None

3. Optimization

None

4. Bug Fixes

1. Hot fix for camera is not working correctly when upgrading firmware from 118.15.0.11 to 118.15.0.20 directly.

Yealink VC210 Teams Collaboration Bar Release Notes of Version 118.15.0.20

1. Introduction

- Firmware Version: 118.15.0.20
- Teams Version: 1449/1.0.94.2020040901
- Partner APP Version: 1.15.0.20040919
- Applicable Models: VC210
- CP900 Firmware: 100.420.0.15
- Release Date: May 9th, 2020.

2. Feature List

1. Supported Meet Now.
2. Supported 1080P UI for better experience on content viewing.
3. Supported the bundle upgrade for audio pack when upgrading the firmware
- no need for user to have a tool to manage CP900.

3. Optimization

1. Optimized the experience of auto framing.

4. Bug Fixes

1. Fixed an issue that In-call Preview video is very low quality (pixelated).
2. Fixed an issue that Reset user settings not working properly.
3. Fixed an issue that Escape (^) character is missing in keyboard.
4. Fixed an issue that Cannot disable screensaver once enabled.

5. Features Descriptions

None