

Yealink SIP IP Phones Release Notes of Version 86

Table of Contents

Yealink SIP IP Phones Release Notes of Version 86	1
Yealink SIP IP Phones Release Notes of Version x.86.0.45	2
1. Statement	2
2. Introduction.....	2
3. New Features	3
4. Optimization.....	3
5. Bug Fixes.....	3

Yealink SIP IP Phones Release Notes of Version x.86.0.45

1. Statement

To reduce the issues from the supply chain, Yealink has developed multiple backup solutions to ensure a long-term, sustainable, and regular supply. Based on the premise of guaranteeing supplier qualification, Yealink will purchase identical quality devices from at least two different suppliers in advance.

Moreover, to be compatible with devices from different vendors and ensure product quality and stability, Yealink has updated the hardware for T3X, T4XU, and T5XW series on this release.

1. We have added a V2 logo on the new hardware and limited the software downgrading on the following devices:

- For T3X series with V2 hardware, the available firmware version is 124.86.0.40 or above.
- For T4XU series with V2 hardware, the available firmware version is 108.86.0.45 or above.
- For T5XW series with V2 hardware, the available firmware version is 96.86.0.45 or above.

2. Introduction

- Firmware Version:

T57W/T54W/T53C/T53/T53W: 96.86.0.23 upgrades to 96.86.0.45

T30/T30P/T31/T31P/T31G/T33P/T33G: 124.86.0.20 upgrades to 124.86.0.40

T42U/T43U/T46U/T48U: 108.86.0.20 upgrades to 108.86.0.45

- Applicable Models: T30, T30P, T31, T31P, T31G, T33P, T33G, T53, T54, T57, T53W, T54W, T57W, T53C, T42U, T43U, T46U, T48U

- Release Date: Dec 17th, 2021.

3. New Features

None.

4. Optimization

None.

5. Bug Fixes

[T5X] Fixed the issue that the devices became bricked when you failed to upgrade the firmware from V85 to a higher version.
Now, the phone will automatically return to the previous version when you fail to upgrade it because of power failure or network disconnection.