Yealink MVC Series Video Solution Release Notes of Version 22

Table of Contents

Yealink MVC Series Video Solution Release Notes of Version x.422.0.15

1. Introduction

● Firmware Version:

UVC40: 128.410.0.10 upgrades to 128.410.0.30

UVC50: 92.421.0.10 upgrades to 92.422.0.15

UVC80: 92.421.0.10 upgrades to 92.422.0.15

Camera-Hub: 84.421.0.5 upgrades to 84.422.0.15

Yealink RoomConnect Software: 2.2.45.0 upgrades to 2.22.24.0

● Applicable Models: UVC40, UVC50, UVC80, Camera-Hub, Camera Control Plug-in Software (Yealink RoomConnect)

● Release Date: January 25th, 2021.

2. New Features

1. Added the feature that UVC40 can work with Barco CX series product. UVC40 supports direct sharing in Zoom Room.

2. Added the feature that UVC50 & UVC80 (MVC500 II & MVC800 II) support VCM38 ceiling microphone (Up to 8) and multiple MSpeaker II (Up to 4) video conferencing soundbars.

3. Added the feature that Camera-Hub (MVC900 II) supports VCM38 ceiling microphone (Up to 8) and multiple MSpeaker II (Up to 4) video conferencing soundbars.

4. Added the feature that you can enable or disable the Auto Framing feature of each UVC80 for Camera-Hub (MVC900 II) via camera control plug-in software.

3. Optimization

None

4. Bug Fixes

None

5. Points for Attention

For UVC40, before upgrade to latest firmware, please update Yealink RoomConnect

Software to the latest version first.