

## Yealink MVC Series Video Solution Release Notes of Version 21

### Table of Contents

Yealink MVC Series Video Solution Release Notes of Version 21 .....	1
Yealink MVC Series Video Solution Release Notes of Version x.421.0.5 .....	2
1. Introduction .....	2
2. New Features.....	2
3. Optimization.....	2
4. Bug Fixes.....	3
5. Points for Attention.....	3

## Yealink MVC Series Video Solution Release Notes of Version x.421.0.5

### 1. Introduction

- Firmware Version:

MShare: 94.420.0.5 upgrades to 94.421.0.10

UVC50: 92.420.0.15 upgrades to 92.421.0.5

UVC80: 92.420.0.15 upgrades to 92.421.0.5

Camera Control Plug-in Software: 2.0.14.0 upgrades to 2.1.17.0

Camera-Hub: 84.421.0.5

CP960: 73.20.0.15

- Applicable Models: MShare, UVC50, UVC80, Camera Control Plug-in Software (Yealink RoomConnect)
- Release Date: Mar 13<sup>th</sup>, 2020.

### 2. New Features

1. Added the feature of auto-framing and people counting for UVC50 and UVC80.
2. Added the feature that you can adjust camera layout for MVC900.
3. Added the feature that the auto update is supported by Yealink RoomConnect for peripherals, including MShare, UVC50 & UVC80 camera, CP900, Yealink Camera Control Plug-in.
4. Added the feature of USB mode for CP960.

### 3. Optimization

None

## **4. Bug Fixes**

1. Fixed an issue about wireless content sharing.

## **5. Points for Attention**

1. Auto-framing feature for UVC50 & UVC80 is a preview feature (trial version). It is disabled by default, users can enable this feature via Yealink Camera Control Plug-in. You should upgrade Yealink RoomConnect and UVC80/50 Camera at the same time to make auto-framing feature available.