

Yealink MVC Series Video Solution Release Notes of Version 20

Table of Contents

Yealink MVC Series Video Solution Release Notes of Version 20	1
Yealink MVC Series Video Solution Release Notes of Version x.420.0.15	2
1. Introduction.....	2
2. New Features.....	2
3. Optimization.....	2
4. Bug Fixes	3
5. Points for Attention	3

Yealink MVC Series Video Solution Release Notes of Version x.420.0.15

1. Introduction

- Firmware Version:
MShare: 94.11.0.20 upgrades to 94.420.0.5
UVC30: 105.410.0.5 upgrades to 105.420.0.10
UVC50: 92.11.0.10 upgrades to 92.420.0.15
UVC80: 92.11.0.10 upgrades to 92.420.0.15
Camera Control Plug-in Software: 1.3.6.0 upgrades to 2.0.14.0
- Applicable Models: MShare, UVC30, UVC50, UVC80, Camera Control Plug-in Software (Yealink RoomConnect)
- Release Date: Nov 29th, 2019.

2. New Features

1. Developed the new user interface for Yealink RoomConnect.
2. Added the feature that you can upgrade device firmware (including UVC cameras, MShare and CP900) via Yealink RoomConnect tool in Windows admin mode.
3. Added the feature that you can upgrade device firmware via Yealink Device Management Platform/Cloud Service.
4. Added the feature that Yealink WPP20 Wireless Presentation Pod is compatible with macOS.

3. Optimization

None

4. Bug Fixes

1. Fixed an issue about Windows Update.

5. Points for Attention

In Version20, you should upgrade Yealink RoomConnect and UVC80/50 Camera at the same time to make the camera PTZ control available. For the early version, the firmware of Camera Control Plug-in and UVC50/80 may be pushed separately in different time by Windows Update, which may cause camera PTZ control unavailable.

In this case, if the PTZ control is unavailable, please do one of the following:

- (1) Switch Skype account to Windows admin account, go to **Settings** -> **Update & Security** -> **Windows Update**, and then press "**check for updates**" to perform Windows Update manually.
- (2) Download the installation package of Version20 from the following link and install it. After installation, all drivers and firmware will be updated to the latest version.

https://drive.google.com/open?id=18ATyP0jqDt88vObtsINJe_JRIw4yC8XN

Note: Devices that already running Version11 will not be affected by this case.