

## Yealink VCS2.0 Endpoint Release Notes Version 44 SP2

### Contents

Yealink VCS2.0 Endpoint Release Notes Version 44 SP2 .....	1
Yealink VCS2.0 Endpoint Release Notes Version x.44.0.30 .....	2
1. Version Introduction .....	2
2. New Features .....	2
3. Optimizations .....	2
4. Bug Fixes.....	2

## Yealink VCS2.0 Endpoint Release Notes Version

### x.44.0.30

#### 1. Version Introduction

- Firmware Version:
  - VC800: 63.44.0.25 upgraded to 63.44.0.30
  - VC880: 63.44.0.25 upgraded to 63.44.0.30
  - VC500: 63.44.0.25 upgraded to 63.44.0.30
  - VC200: 80.44.0.25 upgraded to 80.44.0.30
  - VCC22: 63.44.0.25 upgraded to 63.44.0.30
  - CTP20: 85.44.0.25 upgraded to 85.44.0.35
- Applicable Model: VC800, VC500, VC880, VC200, VCC22, CTP20
- Release Date: December 15<sup>th</sup>, 2020

#### 2. New Features

None

#### 3. Optimizations

1. Adjusted the factory configured Demo contacts: remove the invalid Yealink Demo5 and Yealink Demo6 contacts; modify the address of Yealink Demo3 contact to *117.28.234.40##70000* to ensure that the call can be made normally.

#### 4. Bug Fixes

1. Solved the issue that some VCH51 are not available to use.