

Yealink SIP IP Phones Release Notes 3CX Edition

1. Introduction

• Firmware Version:

T19P: 31.71.0.225 Upgrade to 31.71.0.228

T21P: 34.71.0.225 Upgrade to 34.71.0.227

- Applicable Models: SIP-T19P/T21P
- Release Date: Oct 29th, 2014.

2. New features

No new features added on the new commercial version.

3. Bug fixes

- 1. Fixed the issue that the caller-id display could not be replaced correctly after using call pickup.
- 2. T19P: Fixed the issue that the "Action URI: key = HOLD" could not be taken effect.



Yealink SIP IP Phones Release Notes 3CX Edition

1. Introduction

• Firmware Version:

T19P: 31.71.0.35 Upgrade to 31.71.0.225 T21P: 34.71.0.76 Upgrade to 34.71.0.225

- Applicable Models: SIP-T19P/T21P
- Release Date: June 19th, 2014.

2. New features

1. Added the language support of Russian to the T21P and T19P.

3. Optimization

4. Bug Fixes

1. Fixed the issue that the BLF doesn't work under 3CX SBC environment.