

Yealink UVC40-128.410.0.40 Build Release Notes

Table of Contents

Yealink UVC40-128.410.0.40 Build Release Notes	1
1. Yealink UVC40-128.410.0.40 Build Release Notes Introduction	2
2. New Features.....	2
3. Optimization.....	2
4. Bug Fixes.....	2
5. Points for Attention.....	2

1. Yealink UVC40-128.410.0.40 Build Release Notes

Introduction

- Firmware Version:
UVC40: 128.410.0.30 upgrades to 128.410.0.40
- Applicable Models: UVC40
- Release Date: April 19, 2021

2. New Features

None

3. Optimization

Image quality improvement

4. Bug Fixes

Minor bug fixes

5. Points for Attention

After upgrade UVC40 to latest firmware, please update Yealink RoomConnect Software to the latest version **2.22.40.0** at the same time for best using experience. You can check for update to get the latest version of Yealink RoomConnect.