

Yealink UVC84-262.410.0.40 Build Release Notes

Table of Contents

Yealink UVC84-262.410.0.40 Build Release Notes	1
1. Yealink UVC84-262.410.0.40 Build Release Notes Introduction	2
2. New Features.....	2
3. Optimization.....	2
4. Bug Fixes.....	2
5. Points for Attention.....	2

1. Yealink UVC84-262.410.0.40 Build Release Notes

Introduction

- Firmware Version:
UVC84: 262.410.0.15 upgrades to 262.410.0.40
- Applicable Models: UVC84
- Release Date: April 23, 2021

2. New Features

None

3. Optimization

None

4. Bug Fixes

Fix some image focus issue.

5. Points for Attention

After upgrade UVC84 to latest firmware, please update Yealink RoomConnect Software to the latest version **2.22.40.0** at the same time for best using experience. You can check for update to get the latest version of Yealink RoomConnect.