

Yealink VCS2.0 Endpoint Release Notes Version 45

Table of Contents

Yealink VCS2.0 Endpoint Release Notes Version 45	1
Yealink VCS Endpoint Release Notes Version x.45.0.x	2
1. Version Introduction.....	2
2. New Features	2
3. Optimization	2
4. Bug Fixes.....	3

Yealink VCS Endpoint Release Notes Version x.45.0.x

1. Version Introduction

- Firmware Version:
VC800: 63.44.0.30 upgraded to 63.345.0.1
VC500: 63.44.0.30 upgraded to 63.345.0.1
VC880: 63.44.0.30 upgraded to 63.345.0.1
VC200: 80.44.0.30 upgraded to 80.345.0.1
UVC84: 262.410.0.45
VCC22: 63.345.0.1
CTP18: 137.351.0.20
CTP20: 85.351.0.20
CP960: 73.351.0.1
MSpeaker II: 98.422.0.20
- Applicable Model: VC800, VC500, VC880, VC200, VCC22, UVC84, CP960, CTP20, CTP18, MSpeaker II
- Release date: June 1th, 2021.

2. New Features

1. Supported using VCC22 and UVC84 (up to 9 units) with VC880/VC800.
2. Supported using CTP18 with VC880/VC800/VC500/VC200 via a network cable or Wi-Fi connection.
3. Supported using CP700/CP900 with VC200 via a USB cable or BT50, covering the audio need in small and huddle meeting rooms.

3. Optimization

1. Adjusted Yealink Demo Contacts according to Yealink Meeting and YMS.
2. Removed the features of website snapshot to protect user privacy.
3. Supported controlling the resolution/frame rate of the video/content from both the receiver and sharer.

4. Supported disabled the notification when a participant joins or leaves the conference.
5. Added and optimized some API commands of the control system. Also, we updated the document *API Commands Introduction for Yealink Video Conferencing System* to version 1.09.
 - Supported getting and controlling the status of the shared content or whiteboard.
 - Supported configuring Yealink Meeting or YMS accounts.
 - Supported getting and controlling the status of the multi-camera.

4. Bug Fixes

1. Fixed the compatibility issue with some UGREEN USB to RS232 cables.