

Yealink Teams HD IP Phones Release Notes of Version 15

Table of Contents

Yealink Teams HD IP Phones Release Notes of Version 15.....	1
Yealink Teams HD IP Phones Release Notes of Version 58.15.0.131 (T5X) & 73.15.0.126 (CP960) & 122.15.0.44 (MP5X)	4
1. Introduction	4
2. Feature List	4
3. Optimization	4
4. Bug Fixes	5
Yealink Teams HD IP Phones Release Notes of Version 58.15.0.124 (T5X) & 73.15.0.117 (CP960) & 122.15.0.36 (MP5X)	6
1. Introduction	6
2. Feature List	6
3. Optimization	7
4. Bug Fixes	7
5. Features Descriptions	7
Yealink Teams HD IP Phones Release Notes of Version 58.15.0.122 (T5X) & 73.15.0.115 (CP960) & 122.15.0.33 (MP5X)	10
1. Introduction	10
2. Feature List	10
3. Optimization	10
4. Bug Fixes	10
5. Features Descriptions	11
Yealink Teams HD IP Phones Release Notes of Version 58.15.0.118 (T5X) & 73.15.0.111 (CP960) & 122.15.0.27 (MP5X)	12
1. Introduction	12
2. Feature List	12
3. Optimization	13
4. Bug Fixes	13
5. Features Descriptions	13
6. Optimization Descriptions	14
7. Notes	14
Yealink Teams HD IP Phones Release Notes of Version 58.15.0.116 (T5X) & 73.15.0.109 (CP960) & 122.15.0.23 (MP56)	15
1. Introduction	15
2. Feature List	15
3. Optimization	15

4. Bug Fixes	15
5. Features Descriptions	16
Yealink Teams HD IP Phones Release Notes of Version 58.15.0.110 (T5X) & 73.15.0.105 (CP960) & 122.15.0.13 (MP56).....	19
1. Introduction	19
2. Feature List.....	19
3. Optimization.....	19
4. Bug Fixes	19
5. Features Descriptions	20
6. Notes.....	21
Yealink Teams HD IP Phones Release Notes of Version 58.15.0.107 (T5X) & 73.15.0.103 (CP960) & 122.15.0.11 (MP56).....	22
1. Introduction	22
2. Feature List.....	22
3. Optimization.....	23
4. Bug Fixes	23
5. Features Descriptions	24
Yealink Teams HD IP Phones Release Notes of Version 58.15.0.104 (T5X) & 73.15.0.100 (CP960)	25
1. Introduction	25
2. Feature List.....	25
3. Optimization.....	25
4. Bug Fixes	25
5. Features Descriptions	26
Yealink Teams HD IP Phones Release Notes of Version 58.15.0.100	27
1. Introduction	27
2. Feature List.....	27
3. Optimization.....	27
4. Bug Fixes	27
5. Features Descriptions	27
6. Optimization Descriptions.....	28
Yealink Teams HD IP Phones Release Notes of Version x.15.0.96	29
1. Introduction	29
2. Feature List.....	29
3. Optimization.....	29
4. Bug Fixes	29
5. Features Descriptions	30
6. Optimization Descriptions.....	30
7. Notes.....	30
Yealink Teams HD IP Phones Release Notes of Version x.15.0.85	31
1. Introduction	31
2. Feature List	31
3. Optimization	31
4. Bug Fixes	31

5. Features Descriptions	32
6. Optimization Descriptions.....	32
Yealink Teams HD IP Phones Release Notes of Version x.15.0.53	34
1. Introduction	34
2. Feature List.....	34
3. Optimization.....	34
4. Bug Fixes	34
5. Features Descriptions	35
Yealink Teams HD IP Phones Release Notes of Version x.15.0.41	36
1. Introduction	36
2. Feature List.....	36
3. Optimization.....	36
4. Bug Fixes	36
5. Features Descriptions	37
6. Optimization Descriptions.....	37
Yealink Teams HD IP Phones Release Notes of Version x.15.0.38	38
1. Introduction	38
2. Feature List.....	38
3. Optimization.....	38
4. Bug Fixes	38
5. Features Descriptions	39
Yealink Teams HD IP Phones Release Notes of Version x.15.0.36	41
1. Introduction	41
2. Feature List.....	41
3. Optimization.....	41
4. Bug Fixes	42
5. Features Descriptions	42
Yealink Teams HD IP Phones Release Notes of Version x.15.0.20	44
1. Introduction	44
2. Feature List.....	44
3. Optimization.....	45
4. Bug Fixes	45
5. Features Descriptions	45

Yealink Teams HD IP Phones Release Notes of Version 58.15.0.131 (T5X) & 73.15.0.126 (CP960) & 122.15.0.44 (MP5X)

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.124 upgrades to 58.15.0.131
 - T56A: 58.15.0.124 upgrades to 58.15.0.131
 - T55A: 58.15.0.124 upgrades to 58.15.0.131
 - CP960: 73.15.0.117 upgrades to 73.15.0.126
 - MP54: 122.15.0.36 upgrades to 122.15.0.44
 - MP56: 122.15.0.36 upgrades to 122.15.0.44
 - MP58: 122.15.0.36 upgrades to 122.15.0.44
- Teams Version: 1449/1.0.94. 2021051303
- Partner APP Version: 1.15.0.21041414
- Applicable Models: T55A, T56A, T58A, CP960, MP54, MP56, MP58
- Release Date: June 7th, 2021

2. Feature List

1. Supported that integrating Outlook contacts in people app in read-only mode.
2. Supported that the phone enables DTMF on the pre-call screen.
3. Supported that organizer and presenter can set hard mute in a meeting.
4. Supported the live captions during calls.
5. Supported that hides the name of meeting titles.
6. Supported that auto answer for meet now.

3. Optimization

1. Optimized calling latency.

4. Bug Fixes

1. Fixed an issue that the phone reboot slowly.
2. [MP58] Fixed an issue that the phone is not read some letters and numbers in screen reader mode.
3. [T56A] Fixed an issue that the phone export the configuration file is empty.
4. [T55A/MP54] Fixed an issue that the phone cannot search the network using the Wi-Fi dongle.
5. [CP960] Fixed an issue that the phone responds long after pressing the mute button.
6. Fixed an issue that firmware update using Wi-Fi failed in DM.
7. Fixed an issue that the phone needs to sign in again after rebooting.
8. Fixed an issue that shared account sign-in got stuck on verifying few things page in TAC.
9. Fixed an issue that the phone is stuck on the username page while signing in when language (Turkish) is changed from the sign-in page.
10. Fixed an issue that the phone goes back to the sign in screen with the same code when sign in failed.

Yealink Teams HD IP Phones Release Notes of Version 58.15.0.124 (T5X) & 73.15.0.117 (CP960) & 122.15.0.36 (MP5X)

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.122 upgrades to 58.15.0.124
 - T56A: 58.15.0.122 upgrades to 58.15.0.124
 - T55A: 58.15.0.122 upgrades to 58.15.0.124
 - CP960: 73.15.0.115 upgrades to 73.15.0.117
 - MP54: 122.15.0.33 upgrades to 122.15.0.36
 - MP56: 122.15.0.33 upgrades to 122.15.0.36
 - MP58: 122.15.0.33 upgrades to 122.15.0.36
- Teams Version: 1449/1.0.94.2021022403
- Partner APP Version: 1.15.0.21030311
- Applicable Models: T55A, T56A, T58A, CP960, MP54, MP56, MP58
- Release Date: March 30th, 2021

2. Feature List

1. Supported the new and simple sign-in experience.
2. Supported multi-cloud sign-in.
3. Supported signing in from Teams Admin Center and remote provisioning.
4. Supported new meeting stage.
5. Supported LLDP for E911 updates.
6. Supported transferring call to work voicemail.
7. Supported opting out of call queues from Teams phone settings.
8. [CP960] Supported proximity join.
9. Supported HTTPS proxy server.
10. Supported the safer device web.
11. Supported Yealink USB headset UH33 E2, UH34, UH36, and wireless headset WH62, WH63, WH66 and WH67.
12. Supported noise suppression.

3. Optimization

None


4. Bug Fixes

1. Fixed an issue that the account without DID, Teams App crashes after pressing hard keys randomly.

5. Features Descriptions


1. Supported the new and simple sign-in experience.

Description: Users are provided with the option to sign in from any browser or smartphone with a prominent device code. If users choose to sign in from the device, they can enter their username and password on-screen via the device keyboard.



2. Supported multi-cloud sign-in.

Description: For authentication into specialized clouds, users can choose the Settings gear on the sign in page to see the options that are applicable to their tenant.



3. Supported signing in from Teams Admin Center and remote provisioning.

Description: For authentication into specialized clouds, users can choose the Settings gear on the sign in page to see the options that are applicable to their tenant.

4. Supported new meeting stage.


Description: For authentication into specialized clouds, users can choose the Settings gear on the sign in page to see the options that are applicable to their tenant.

5. Supported LLDP for E911 updates.

Description: Teams devices connected to the network via Ethernet will dynamically update location information for emergency calling services based on changes to network attributes including chassis ID and port ID.

6. Supported transferring call to work voicemail.

Description: Users can directly transfer a call into someone's work voicemail without needing to ring the far-end user. This allows them to discreetly leave voicemails for users without interrupting them.



7. Supported opting out of call queues from Teams phone settings.

Description: Call queue agents can opt out of call queues or opt in based on settings made available on the Teams phones.

Mon Feb 01 6:56 PM

←

Calls

TEST_TEST_IPPHONE_TEST

Delegated calls

Default

Call views

Default view

Speed dial

Block calls

Block calls with no caller ID

☐

Blocked numbers

>

Call queues

Disable a queue to opt out. Your admin may control this setting.

Test Call Queue2

☒

Yealink Teams HD IP Phones Release Notes of Version 58.15.0.122 (T5X) & 73.15.0.115 (CP960) & 122.15.0.33 (MP5X)

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.118 upgrades to 58.15.0.122
 - T56A: 58.15.0.118 upgrades to 58.15.0.122
 - T55A: 58.15.0.118 upgrades to 58.15.0.122
 - CP960: 73.15.0.111 upgrades to 73.15.0.115
 - MP54: 122.15.0.27 upgrades to 122.15.0.33
 - MP56: 122.15.0.27 upgrades to 122.15.0.33
 - MP58: 122.15.0.27 upgrades to 122.15.0.33
- Teams Version: 1449/1.0.94.2020111101
- Partner APP Version: 1.15.0.20121622
- Applicable Models: T55A, T56A, T58A, CP960, MP54, MP56, MP58
- Release Date: Dec 29th, 2020

2. Feature List

None

3. Optimization

1. Optimized the popup of the Time Zone after firmware upgrade.

4. Bug Fixes

1. Fixed an issue that reports unknown license error when importing license.
2. Fixed an issue that Time zone change to +8 after firmware upgrade.

5. Features Descriptions

None

Yealink Teams HD IP Phones Release Notes of Version 58.15.0.118 (T5X) & 73.15.0.111 (CP960) & 122.15.0.27 (MP5X)

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.116 upgrades to 58.15.0.118
 - T56A: 58.15.0.116 upgrades to 58.15.0.118
 - T55A: 58.15.0.116 upgrades to 58.15.0.118
 - CP960: 73.15.0.109 upgrades to 73.15.0.111
 - MP56: 122.15.0.23 upgrades to 122.15.0.27
 - MP54: 122.15.0.27
 - MP58: 122.15.0.27
- Teams Version: 1449/1.0.94.2020111101
- Partner APP Version: 1.15.0.20111616
- Applicable Models: T55A, T56A, T58A, CP960, MP54, MP56, MP58
- Release Date: Dec 9th, 2020

2. Feature List

1. Supported MP54 and MP58 Teams IP phones.
2. [T56A/T58A/MP56/MP58] Supported sidecar for phones.
3. Supported talkback/ voice assistant.
4. Supported GCC environment.
5. Supported Meet Now on phones.
6. [T56A/T58A/MP56/MP58] Supported screen sharing.
7. Supported configuring ringer device on phones.
8. [CP960] Supported CP cascade mode.
9. Supported Japanese language and Japanese input method.
10. Supported putting an incoming SIP call to waiting mode when having a Teams call.

3. Optimization

1. Optimized the Time Zone setting: Keyword search, Automatic daylight saving time.

4. Bug Fixes

1. Fixed an issue that multiple issues occurred when Hot Desking performed with Accessibility settings enabled.
2. Fixed an issue that Teams App is crashing when the second call received on the phone.
3. Fixed an issue that user cannot accept the meeting invite from connected Laptop or phone in BT mode.
4. Fixed an issue that the username is not displayed for speed dial contacts.
5. Fixed an issue that show meeting update on home screen till meeting ends.

5. Features Descriptions

1. [T56A/T58A/MP56/MP58] Supported sidecar for phones.

Description: Teams in sidecar gives user an efficient way to reach out for frequently used contact groups in their IP phone. With a sidecar device equipped with Teams, a user can select and pin the names of any contact group in his/her IP phone to the screen of the sidecar, so they can make a speed dial with one click, know their presences at a glance, and manage contacts quickly.



2. Supported GCC environment.

Description: Teams phones application is ready to be deployed in the Microsoft 365 Government – GCC environment.

3. Supported Meet Now on phones.

Description: Users can start an instant meeting on Teams phones from the calendar application. Once the meeting is created, users can add participants by inviting them.

4. Supported configuring ringer device on phones.

Description: You can connect a USB speakerphone CP900 / CP700 on the phone to control calls. When there is an incoming call, the CP900/CP700 will ring and the LED flashes. After answering the call, users can press the button on Teams phone to switch the desired voice channel.

5. [CP960] Supported CP cascade mode.

Description: You can cascade multiple units of CP960 in the same software version for the voice need in the oversized meeting room. You can connect a master and three slaves. The master supports full features but slaves only support basic calling feature.

6. Supported putting an incoming SIP call to waiting mode when having a Teams call.

Description: If you have an incoming SIP call when having a Teams call, the incoming call is set to waiting mode automatically.

6. Optimization Descriptions

1. Optimized the Time Zone setting: Keyword search, Automatic daylight saving time.

Description: You can find time zone with location description or keyword search. The daylight saving time will be set automatically after selecting the time zone.

7. Notes

1. Due to program updates, users need to reset the time zone or TAC (Teams Admin Center) pushes the time zone again after upgrading the new firmware to the newest version.
2. Due to a known issue that the sidebar may trigger the bug of displaying "sign in your account" window on secondary interfaces. New Teams APP solved this issue will be released by Microsoft on TAC.

Yealink Teams HD IP Phones Release Notes of Version 58.15.0.116 (T5X) & 73.15.0.109 (CP960) & 122.15.0.23 (MP56)

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.110 upgrades to 58.15.0.116
 - T56A: 58.15.0.110 upgrades to 58.15.0.116
 - T55A: 58.15.0.110 upgrades to 58.15.0.116
 - CP960: 73.15.0.105 upgrades to 73.15.0.109
 - MP56: 122.15.0.13 upgrades to 122.15.0.23
- Teams Version: 1449/1.0.94.2020091801
- Partner APP Version: 1.15.0.20091610
- Applicable Models: T55A, T56A, T58A, CP960, MP56
- Release Date: Oct 14th,2020

2. Feature List

1. [T56A/T58A/MP56] Supported Better Together Lock/Unlock.
2. [T56A/T58A/MP56] Supported Better Together Meeting scenarios.

3. Optimization

None

4. Bug Fixes

1. Fixed an issue that the device is stuck at "signing-in" page when clicked on company portal option in Settings.
2. Fixed an issue that the offline banner needs to be updated to global offline banner for hidden tabs.
3. Fixed an issue that the laptop is displaying as connected in manage devices even after Desktop Client user logoff.

4. Fixed an issue that the high Contrast Mode does not take effect unless the app is restarted.
5. Fixed an issue that the device is stuck in "Verifying a few things" page while signing in.

5. Features Descriptions

1. [T56A/T58A/MP56] Supported Better Together Lock/Unlock.

Description: Your Teams phone and Teams PC client will have a coordinated and seamless lock and unlock experience.

To set this up, you will need to connect your Teams PC client to your Teams phone.


Prerequisites:

- 1) Both devices need to be signed into the same user account.
- 2) Your PC must be Bluetooth enabled and in proximity to your Teams phone.
- 3) Your PC must run 64-bit Teams desktop client with version \geq 1.3.00.15364.


Note: Mac, Linux, web, mobile and 32-bit/ARM-based Teams clients are currently not supported.

Lock / unlock setup:


- 1) Go to Manage devices on your Teams phone.




- 2) Click Find a device and Connect to setup with your nearby Teams Windows Desktop client.



- 3) Teams phone is waiting for a response from your Teams Windows Desktop client.



- 4) Click Connect on your Teams Windows Desktop client to complete setup with your Teams phone.



- 5) Setup is complete.

Thu Oct 15 10:28 AM

← Manage devices

Connect your own device to access your Teams account.

+ Find a device

YL0817-A03815NB
Active

Disconnect

2. [T56A/T58A/MP56] Supported Better Together Meeting scenarios.

Description: While in a meeting using better together mode on a PC, the call will automatically be routed to the connected device. The connected device will be shown in device settings in the pre-join screen. Once the user has joined the meeting, the call control for same meeting can be accessed from either the connected phone or Teams Windows client.

Yealink Teams HD IP Phones Release Notes of Version 58.15.0.110 (T5X) & 73.15.0.105 (CP960) & 122.15.0.13 (MP56)

1. Introduction

- **Firmware Version:**
T58A: 58.15.0.107 upgrades to 58.15.0.110
T56A: 58.15.0.107 upgrades to 58.15.0.110
T55A: 58.15.0.107 upgrades to 58.15.0.110
CP960: 73.15.0.103 upgrades to 73.15.0.105
MP56: 122.15.0.11 upgrades to 122.15.0.13
- **Teams Version:** 1449/1.0.94.2020071702
- **Partner APP Version:** 1.15.0.20073021
- **Applicable Models:** T55A, T56A, T58A, CP960, MP56
- **Release Date:** Sep 4th,2020

2. Feature List

1. Supported Home screen or landing page for IP phones.
2. Supported Teams button on MP56 phones.
3. Supported touch console mode on CP960 to work with VC210.
4. Supported customizing default view in Calls App.
5. Supported meeting reminders for IP phones.

3. Optimization

None


4. Bug Fixes

None

5. Features Descriptions

1. Supported Home screen or landing page for IP phones.

Description: The home screen on Teams phones is a simple view providing up-to-date information about your calling and meeting activity. You can see meeting reminders of your current and upcoming meetings, perform quick actions like joining your current meeting, playing voicemail, or replying to missed calls directly from your home screen. Detailed information about your call history, calendar and people is still just a click away.



2. Supported Teams button on MP56 phones.

Description: Press the Teams button, it would quickly launch the home screen if the setting is enabled. When home screen is not enabled, the Teams button will always launch the Calls app.

3. Supported touch console mode on CP960 to work with VC210.

Description: You can initiate a pairing request on CP960 and agree on the VC210 device, the CP960 device will enter the touch remote control mode.

4. Supported customizing default view in Calls App.

Description: The phone provides customers the ability to choose whether dial pad is default or speed dial/recent is default under Calling Settings.

5. Supported meeting reminders for IP phones.

Description:

- 1) Show upcoming meeting notifications for upcoming meetings 15 min, 10 min and 5 min before the meeting starts.
- 2) Show options to snooze and dismiss. Snooze again in 10 min and 5 min.
- 3) Meeting started notifications should pop up after meeting has started when the first person or room joins the meeting.

6. Notes

1. Due to Android Security patch update, you are not allowed to downgrade MP56 to the previous versions or switch it to SfB edition. Teams switch to SfB would be support in the next SfB GA release.
Please contact our technical support team for help if it is necessary for you.

Yealink Teams HD IP Phones Release Notes of Version 58.15.0.107 (T5X) & 73.15.0.103 (CP960) & 122.15.0.11 (MP56)

1. Introduction

- **Firmware Version:**
 - T58A: 58.15.0.104 upgrades to 58.15.0.107
 - T56A: 58.15.0.104 upgrades to 58.15.0.107
 - T55A: 58.15.0.104 upgrades to 58.15.0.107
 - CP960: 73.15.0.100 upgrades to 73.15.0.103
 - MP56: 122.15.0.11
- **Teams Version:** 1449/1.0.94.2020051601
- **Partner APP Version:**
 - T55A/T56A/T58A: 1.15.0.20052919
 - CP960: 1.15.0.20052919
 - MP56: 1.15.0.20052820
- **Applicable Models:** T55A, T56A, T58A, CP960, MP56
- **Release Date:** Jun 30th, 2020

2. Feature List

For T55A, T56A, T58A, CP960:

1. Supported Contacts groups.
2. Supported Global network banner.
3. Supported Call merge.
4. Supported Raise Hands.

For MP56:

1. Calling
 - (1) Incoming/Outgoing P2P calls
 - (2) In-call controls via UI

- (3) Call hold/Call mute/Call transfer/Call forward
- (4) Cloud PSTN calls
- (5) Synchronized call logs
- (6) Speed dial
- (7) Visual Voicemail
- 2. Calendar and Presence
 - (1) Presence Integration, Presence status control
 - (2) Exchange Calendar Integration
 - (3) Contact Picture Integration
 - (4) Corporate Directory Access
- 3. Contacts
 - (1) See all contact groups
 - (2) Create/delete group/edit group name
 - (3) Add contact from directory/Add contact to specific group/Remove contact from group
- 4. Meetings
 - (1) One-click Join for Meetings
 - (2) Meeting Call controls (Mute/unmute, hold/resume, hang up, add/remove participant)
 - (3) Meeting Details
 - (4) Schedule Teams meeting
 - (5) Join Skype for Business meeting
- 5. Phone Features
 - (1) SIP&Teams Hybrid Mode
 - (2) Sign in with user credentials
 - (3) Accessibility
 - (4) Phone lock/unlock
 - (5) Screensaver
 - (6) Power Saving
 - (7) Wi-Fi
 - (8) Supports USB Headset
 - (9) Supports Bluetooth Headset

3. Optimization

None


4. Bug Fixes

None

5. Features Descriptions

1. Supported Contacts groups.

Description: The Microsoft Teams user can view their contacts when they navigate to the **People** tab.




2. Supported Global network banner.

Description: The phone shows a single banner across all screens that action cannot be completed when there is network loss.

3. Supported Call merge.

Description: You can merge the active call and the held calls on your phone.



Yealink Teams HD IP Phones Release Notes of Version 58.15.0.104 (T5X) & 73.15.0.100 (CP960)

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.100 upgrades to 58.15.0.104
 - T56A: 58.15.0.100 upgrades to 58.15.0.104
 - T55A: 58.15.0.100 upgrades to 58.15.0.104
 - CP960: 73.15.0.96 upgrades to 73.15.0.100
- Teams Version: 1449/1.0.94.2020040801
- Partner APP Version:
 - T55A/T56A/T58A: 1.15.0.20041716
 - CP960: 1.15.0.20041716
- Applicable Models: T55A, T56A, T58A, CP960
- Release Date: May 15th, 2020

2. Feature List

1. Supported account status on YMDP/YMCS.
2. [T55A/T56A/T58A] Supported the compatibility with Yealink EHS40.
3. Supported paging on hybrid mode.
4. [T55A/T56A/T58A] Supported the compatibility with CP900/CP700.
5. Supported Wi-Fi deployment tool.

3. Optimization

1. Optimized the UI on lock screen and screen saver.

4. Bug Fixes

None

5. Features Descriptions

1. Supported account status on YMDP/YMCS.

Description: If you enable the device management feature, the phone supports synchronizing account registration status to YDMP/YMCS.

2. [T55A/T56A/T58A] Supported the compatibility with Yealink EHS40.

Description: You can use most wireless headsets with your phone. EHS40 provides the technical interface between your phone and an EHS-compatible wireless headset, such as Sennheiser/Jabra (GN Netcom) or Plantronics headset. After the EHS40 and your headset are connected successfully, you can handle calls by your headset.

3. Supported paging on hybrid mode.

Description: After the hybrid mode is enabled, users can receive a paging call in the teams app mode.

4. [T55A/T56A/T58A] Supported the compatibility with CP900/CP700.

Description: You can connect a USB speakerphone CP900 / CP700 on the phone to control calls.

5. Supported Wi-Fi deployment tool.

Description: Yealink IP phones can automatically connect to the wireless network via a Yealink-supplied App.

Yealink Teams HD IP Phones Release

Notes of Version 58.15.0.100

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.96 upgrades to 58.15.0.100
 - T56A: 58.15.0.96 upgrades to 58.15.0.100
 - T55A: 58.15.0.96 upgrades to 58.15.0.100
- Teams Version: 1449/1.0.94.2020031901
- Partner APP Version: 1.15.0.20033111
- Applicable Models: T55A, T56A, T58A
- Release Date: April 26th, 2020.

2. Feature List

1. Supported Boss/Admin Delegate Calling Features.
2. Supported Auto-Dial for Extension Calling.
3. Supported Distinctive Ringtones by Call Types.
4. Supported Adding and Removing Favorites.
5. Supported Adding Delegates from Settings.

3. Optimization

1. Optimized the feature of Group Call Pickup.
2. Optimized the User Interface for Calls.

4. Bug Fixes

None

5. Features Descriptions

1. Supported Boss/Admin Delegate Calling Features.

Description: When placing an outgoing call, the delegate can call either on behalf of themselves or on behalf of the boss. Delegates can see and monitor boss' call status on the delegate's phone. When the boss puts a call on hold, call status is reflected on the delegate's phone and the delegate can pick up the call on behalf of the boss.

2. Supported Auto-Dial for Extension Calling.

Description: Tenant admins can add dial plans for their organization with normalization rules to enable extension dialing in Teams. Teams phones will auto dial in 3 seconds after an approved extension is dialed by the user using the dial pad.

3. Supported Distinctive Ringtones by Call Types.

Description: You can set different ringtones for incoming calls, forwarded calls, and delegated calls.

4. Supported Adding and Removing Favorites.

Description: By default, all favorite contacts from the Teams desktop client are marked as favorite contacts on the phone. You can add favorites or remove favorites.

5. Supported Adding Delegates from Settings.

Description: You can add a delegate from Settings.

6. Optimization Descriptions

1. Optimized the feature of Group Call Pickup.

Description: You can accept/decline incoming call notifications for call groups from anywhere on the phone.

2. Optimized the User Interface for Calls.

Description: Update the following user interface for calls:

- Always available dial pad for T56A and T58A devices.
- Quick access with touch-friendly icons for favorite contacts.
- Hidden but accessible view of recent calls for increased privacy.

Yealink Teams HD IP Phones Release Notes of Version x.15.0.96

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.85 upgrades to 58.15.0.96
 - T56A: 58.15.0.85 upgrades to 58.15.0.96
 - T55A: 58.15.0.85 upgrades to 58.15.0.96
 - CP960: 73.15.0.85 upgrades to 73.15.0.96
- Teams Version: 1449/1.0.94.2020020601
- Partner APP Version:
 - T55A/T56A/T58A: 1.15.0.20021214
 - CP960: 1.15.0.20021214
- Applicable Models: T55A, T56A, T58A, CP960
- Release Date: Feb 24th, 2020.

2. Feature List

1. Supported Proxy Server.
2. Supported Hot Desking.

3. Optimization

1. Optimized the feature of Microsoft E911.

4. Bug Fixes

1. Fixed an issue that Lock code may not be reset after the emergency call gets disconnected.
2. Fixed an issue that the partner agent must send FirmwareVersionName in Bundle string instead of FirmwareVersion according to the new Partner Agent design spec.
3. Fixed an issue that the call will go through the speaker instead of the

handset even after the phone is in offhook state.

5. Features Descriptions

1. Supported Proxy Server.

Description: When the phone wants to access the external network from the internal network, it will pass through the proxy server first to ensure communication security.

2. Supported Hot Desking.

Description: Hot Desking allows a temporary account to be used on the phone to meet the needs of mobile office.

6. Optimization Descriptions

2. Optimized the feature of Microsoft E911.

Description: If an emergency issue occurs, the user can use the phone directly to enter the E911 number for alarm at any time.

7. Notes

1. Due to the risk of downgrade, we remove the old versions from the official website. If necessary, contact Yealink technical support team.

Yealink Teams HD IP Phones Release Notes of Version x.15.0.85

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.53 upgrades to 58.15.0.85
 - T56A: 58.15.0.53 upgrades to 58.15.0.85
 - T55A: 58.15.0.53 upgrades to 58.15.0.85
 - CP960: 73.15.0.45 upgrades to 73.15.0.85
- Teams Version: 1449/1.0.94.2019110101
- Partner APP Version:
 - T55A/T56A/T58A: 1.15.0.19110719
 - CP960: 1.15.0.19111109
- Applicable Models: T55A, T56A, T58A, CP960
- Release Date: Nov 27th, 2019.

2. Feature List

1. Supported Wi-Fi.
2. Supported Custom Screensaver.
3. [T55A/T56A/T58A] Supported call status synchronization on USB headset.
4. [CP960] Supported Bluetooth.
5. [CP960] Supported USB Mode.

3. Optimization

1. Upgraded the phone system to Android 7.1.

4. Bug Fixes

1. Fixed an issue that the phone may fail to generate “+” if you long press “0” on the dial pad and the phone screen may not display either.
2. Fixed an issue that the Mute state may not be prompted on Teams app

during the call.

3. Fixed an issue that the incoming call may be rejected automatically while you are playing a voice mail.
4. Fixed an issue that the second digit may be missing if you dial a PSTN number and you press the digit too quickly on the dial pad.
5. Fixed an issue that you may probably hear an echo when using the speaker during the call.
6. Fixed an issue that you may hear a louder background noise if there is no one speaking during the call.

5. Features Descriptions

1. Supported Wi-Fi.

Description: All Yealink Teams phones supported Wi-Fi and Bluetooth. CP960 and T58A is equipped with built-in Wi-Fi and Bluetooth, while T55A and T56A need to work with Wi-Fi USB dongle WF50 and Bluetooth USB dongle BT41.

2. Supported Custom Screensaver.

Description: You can upload custom pictures via WEB UI: Settings -> Preference -> Screensaver. The pictures will be displayed on the screen when Yealink Teams phone enters Screen Saver. If you upload more than 2 pictures, Yealink Teams phone will take turns every 60 seconds to display screensaver pictures.

3. [T55A/T56A/T58A] Supported call status synchronization on USB headset.

Description: After a USB headset is connected to Yealink Teams phone, the USB headset will play the ring tone or the LED indicator will flash if there is an incoming call.

4. [CP960] Supported USB Mode.

Description: After connected to PC via a USB cable, CP960 can be worked as an audio device for PC, supporting voice pickup and audio playback. If there is an incoming call on your Teams Client, CP960 will enter USB mode automatically and you can control the calls (mute, unmute, hang up) on CP960 directly.

6. Optimization Descriptions

1. Upgraded the phone system to Android 7.1.

Description: After you upgrade your Yealink Teams phone to this firmware

version, the phone will run on Android 7.1.

Caution: Do not downgrade your Yealink Teams phone from current firmware with Android 7.1 OS to the previous firmware with Android 5.1 OS. Please contact our technical support team for help if it is necessary for you to downgrade, otherwise, you might run into some troubles.

Yealink Teams HD IP Phones Release Notes of Version x.15.0.53

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.41 upgrades to 58.15.0.53
 - T56A: 58.15.0.41 upgrades to 58.15.0.53
 - T55A: 58.15.0.41 upgrades to 58.15.0.53
 - CP960: 73.15.0.38 upgrades to 73.15.0.45
- Teams Version: 1449/1.0.94.2019082001
- Partner APP Version:
 - T55A/T56A/T58A: 1.15.0.19090415
- Applicable Models: T55A, T56A, T58A, CP960
- Release Date: Sept 24th, 2019.

2. Feature List

1. Supported CAP.
2. Supported Dark Theme.
3. Supported Ringing Multiple Incoming Calls.
4. Supported IP Phone policies.

3. Optimization

None

4. Bug Fixes

1. Fixed an issue that after the outgoing call is cancelled, the ring back tone may still be heard in Teams app.
2. Fixed an issue that after a second call is placed, the Mute LED indicator may not be reset yet.
3. Fixed an issue that if there are two call notifications, it may not be updated automatically after you handled it.

4. Fixed an issue that if the user uses Teams Desktop Client to call the phone installed with Teams app, the phone may not ring but get a missed call notification.
5. Fixed an issue that the cached credentials of the last sign-in may be still used for the next time when you sign into the Teams app.

5. Features Descriptions

1. Supported CAP.

Description: After the user signs into the CAP account, the phone is used directly as a common area phone. The following features are not available for a Common Area Phone:

- The Voicemail feature
- The Teams Meeting Feature
- The Phone Lock feature

2. Supported Dark Theme.

Description: You can enable or disable the Dark theme on the phone via Settings -> Dark theme.

Yealink Teams HD IP Phones Release Notes of Version x.15.0.41

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.38 upgrades to 58.15.0.41
 - T56A: 58.15.0.38 upgrades to 58.15.0.41
 - T55A: 58.15.0.38 upgrades to 58.15.0.41
- Teams Version: 1449/1.0.94.2019062601
- Partner APP Version:
 - T55A/T56A/T58A: 1.15.0.19070913
- Applicable Models: T55A, T56A, T58A
- Release Date: Jul 26th, 2019.

2. Feature List

1. Supported the language of Dutch (Netherlands) for the phone user interface.
2. Supported reset to factory settings without admin password.

3. Optimization

1. Optimized the Teams Feature License.

4. Bug Fixes

1. Fixed an issue that the phone may not able to enter device setting while in calling.
2. Fixed an issue that you may not reset user settings from admin settings.
3. Fixed an issue that the incorrect serial number may be reported in Intune.
4. Fixed an issue that when Large Text is enabled on T55A, the dial pad may not be displayed normally.

5. Features Descriptions

1. Supported the language of Dutch(Netherlands).

Description: You can change the language to Dutch(Netherlands) for the phone user interface.

2. Supported reset to factory settings without admin password.

Description: You can reset to factory settings via long press *and# without admin password.

6. Optimization Descriptions

1. Optimized the Teams Feature License.

Description: By default, the phone has a built-in Teams feature license, which allows user to use Yealink phones with Teams features directly. Any Open SIP build upgrades to Teams build will be required to apply and import the license.

Any Teams upgrades to Skype for Business will not need to be required additional license. And vice versa.

Any Teams will not be allowed to downgrade to the Open SIP from this release. If Teams phones are under temporary license (for demo testing purpose) and want to get back to Open SIP, please contact Yealink support team for technical support for an unlock license.

Once upgraded to the latest Teams, it will not be allowed to downgrade to the previous Teams version.

Yealink Teams HD IP Phones Release Notes of Version x.15.0.38

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.36 upgrades to 58.15.0.38
 - T56A: 58.15.0.36 upgrades to 58.15.0.38
 - T55A: 58.15.0.36 upgrades to 58.15.0.38
 - CP960: 73.15.0.36 upgrades to 73.15.0.38
- Teams Version: 1449/1.0.94.2019031201
- Partner APP Version:
 - T55A/T56A/T58A: 1.15.0.19043022
 - CP960: 1.15.0.19040418
- Applicable Models: T58A, T56A, T55A, CP960
- Release Date: May 15th, 2019.

2. Feature List

1. Supported Hybrid Mode (two APPs running on the phone in the meanwhile: Team APP and Survivability App). Note that this feature will be supported by T55A in September 2019.

3. Optimization

None

4. Bug Fixes

None

5. Features Descriptions

1. Hybrid Mode

Description: Teams phone supports hybrid mode. This feature is suitable for the scenario of disconnection with local MS server. In addition, it can be applied to customers who migrate from SIP solutions to Teams solutions. During the transition period, there will be both SIP account users and Teams account users within the enterprise, and we will make it possible for these two groups to communicate with each other.

To enable hybrid mode on the Teams phone, you need configure these parameters in the CFG file.

```
features.hybrid_mode.enable=1
account.X.sip_server.1.address = <SBC IP Address>
account.X.user_name = <Username>
account.X.password = <Password>    [X ranges from 1 to 12]
```

There are two APPs (Teams APP and Survivability APP) running on the Teams phone. And Yealink Teams phone supports the registration of multiple accounts (including Teams and SIP accounts) on the phone. the user can dial or answer SIP calls on survivability APP.




Figure 1 - Entrance of Survivability APP on Teams APP




Figure 2 – Enabling Quick Ball on Teams APP




Figure 3 - Main Screen of Survivability APP




Figure 4 – Placing a call on Survivability APP

Yealink Teams HD IP Phones Release Notes of Version x.15.0.36

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.20 upgrades to 58.15.0.36
 - T56A: 58.15.0.20 upgrades to 58.15.0.36
 - T55A: 58.15.0.36
 - CP960: 73.15.0.20 upgrades to 73.15.0.36
- Teams Version: 1449/1.0.94.2019031201
- Partner APP Version:
 - T55A/T56A/T58A: 1.15.0.19043022
 - CP960: 1.15.0.19040418
- Applicable Models: T58A, T56A, T55A, CP960
- Release Date: May 14th, 2019.

2. Feature List

1. Unified the firmware of T58A, T56A and T55A. Supported T55A Teams IP phones.
2. Supported Accessibility Features
 - (1) Large Text
 - (2) High Contrast Mode
 - (3) Color Correction
3. Supported emergency call on the lock screen
4. Supported Bluetooth via USB dongle (for T56A/T55A Teams phone only, T58A is armed with built-in Bluetooth)
5. Supported CPE90 wired microphone and CPW90 wireless microphone on CP960 Teams phone.

3. Optimization

None


4. Bug Fixes

None

5. Features Descriptions


1. Using accessibility features

Description: The phone includes a number of features to accommodate vision-impaired users. You can change displayed text size and contrast if any difficulties in reading text on screen. And you can change color mode if any difficulties in color recognition. These features are disabled by default, and after you sign out the current account, the personal configuration for those accessibility features will be reset.



2. Placing emergency call on the lock screen

Description: Once locking the phone, you can dialing an emergency number without having to unlock.




3. Using Bluetooth via USB dongle (for T55A/T56A Teams phone only)

Description: The T58A/T56A/T55A Teams phone supports Bluetooth. You can pair and connect the Bluetooth headset to your phone. Before using Bluetooth feature on T55A and T56A, make sure the Bluetooth USB Dongle BT41 is connected.

4. Using the CP Wireless Expansion Mic CPW90

Description: The Yealink CPW90 is a CP Wireless Expansion Mic which works as an audio input device for CP960 IP phone. It features superior audio technology and supports 360-degree voice pickup range at a radius of up to 10 feet (3 meters) without any wiring troubles. On your phone, navigate to **Settings -> Device Settings** to register CPW90 with the IP phone to use the CPW90 as the external audio input device.



Yealink Teams HD IP Phones Release Notes of Version x.15.0.20

1. Introduction

- Firmware Version:
 - T58A: 58.15.0.20
 - T56A: 58.15.0.20
 - CP960: 73.15.0.20
- Teams Version: 1449/1.0.94.2018121201
- Partner APP Version:
 - T56A/T58A: 1.15.0.19010320
 - CP960: 1.15.0.19010418
- Applicable Models: T58A, T56A, CP960
- Release Date: Jan 7th, 2019.

2. Feature List

1. Calling
 - (1) Incoming/Outgoing P2P calls
 - (2) In-call controls via UI
 - (3) Call hold/Call mute/Call transfer/Call forward
 - (4) Second forwarded if unanswered
 - (5) PSTN calls
 - (6) Synchronized call logs
 - (7) Visual Voicemail
2. Calendar and Presence
 - (1) Presence Integration, Presence status control
 - (2) Exchange Calendar Integration
 - (3) Contact Picture Integration
 - (4) Corporate Directory Access
3. Meetings
 - (1) One-click Join for Meetings
 - (2) Join Skype for Business meetings
 - (3) Meeting Call controls (Mute/unmute, hold/resume, hang up, add/remove participant)

- (4) Meeting Details
- (5) Schedule Teams meeting
- (6) Join Skype for Business meeting
- 4. Phone Features
 - (1) Personal/shared mode
 - (2) Sign in with user credentials
 - (3) Phone lock/unlock
 - (4) Screensaver
 - (5) Power Saving
 - (6) Supports USB Headset (Only applicable to T56A/T58A)
 - (7) Supports Bluetooth Headset (Only applicable to T58A)

3. Optimization

None


4. Bug Fixes

None

5. Features Descriptions


1. Personal/shared mode

Description: After successful sign-in, the user can choose whether the device will be used for personal use or in a shared conference room.




The Teams phone experience is optimized based on the user's selection.

Personal mode




Shared mode




2. Calling experience

Description: The Microsoft Teams user can lift the handset or press the **Speaker** button to launch the dial pad on the calling screen. Alternatively, the user can use the hardware buttons (if available) to dial out a number.

On-screen dial pad




Calling screen




3. Meeting experience

Description: The Microsoft Teams user can navigate to the meetings tab to view their meetings and use the **Join** button to join their Teams meetings.

Calendar view




Meeting join view




4. Voicemail

Description: The Microsoft Teams user can access their voicemail when they navigate to the **Voicemail** tab.



5. Bluetooth

Description: On your phone, navigate to **Settings -> Device Settings** to activate the Bluetooth mode. After that, you can pair and connect the Bluetooth headset to your phone (For the compatible Bluetooth headset, please refer to *Tested headset list compatible with Yealink IP Phone*). Bluetooth feature is only available for T58A Teams phone and now it is not supported PC connection and playing music via Bluetooth.



6. Phone Lock

Description: After the phone is registered with the account, you can navigate to **Settings -> Device Settings** to configure the phone lock feature. If you do not sign into the phone with the account, this feature is not available.

←

Phone settings

✓

User settings

Language

English(United States)

Time & Date

Display

Phone Lock

Bluetooth

Debug

About

Admin only

Network

Debug

Lock Enable

New PIN

.....

Confirm PIN

PIN 's length must be 6 digits

Idle time-out

15min